


100

Fig. 1






Fig 2

FIG. 3




Fig 3




Fig 4




Fig 5




Fig. 6




Fig. 8




Fig. 10

150

158

154

162

160

168

146

141

138

148

142

166

174

172

176




Fig. 11





Fig. 12






Fig. 14






Fig. 15








Fig. 18

FIG. 19




Fig. 19




Fig. 20




Fig. 21




Fig. 22




Fig. 23




Fig. 24




Fig 25

Fig 194

FIG. 260 "3624650"

Balloon

192

Balloon Retraction
Subassembly

120

236

238

Cable Cap

Tube shown
cut in half.

234

236

120

Fluid

Note:

A cable connects the "Tip"
to the "Cable Cap".

Fig 26




Fig 27




Fig 28




Fig 29




Fig 30




Fig 31




Fig. 32




Fig 33




Fig 34




Fig 35




Fig 30

Fig. 37

192 (Extended, inflated position)




Fig. 38



